

**PRODUCT SAFETY RECALL**  
**Hitch Rod Failure:**  
**Issued December 1995**

**MODEL:** SLK7000 SULKY

**SERIAL #'s** All units

**PROBLEM:** If the hitch rod fails, the floor pan will drop on the control rod.  
This may result in injury to the operator.

**WHAT TO DO:** Discontinue use of SLK7000 Sulky and take to your nearest  
Honda authorized dealer. To find the nearest Honda dealer you may check our dealer  
locator on our web site: [www.hondapowerequipment.com](http://www.hondapowerequipment.com) or call toll free 1-888-888-  
3139.